

24 SEP 1964

OUT5414U

1964 SEP 23 22 33Z

P 232147Z
FM NPIC WASHDC *Multi*
TO RUCSBR/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEAHQ/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA

BT
S E C R E T CITE NPIC 2972.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-101 WAS USED IN MISSION 3949 FLOWN ON 22 SEPTEMBER 1964; PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINOR INBOARD EDGE STATIC IS APPARENT IN THE FIRST HALF OF THE MISSION. MINUS DENSITY SPOTS, SPACED 2.3" APART, ARE LOCATED 1.55" FROM THE OUTBOARD EDGE IN FRAMES 255 TO 400. A TRANSVERSE PLUS DENSITY STREAK OCCURS APPROXIMATELY 3.3" FROM THE SUPPLY END OF FRAME 295 AND AGAIN IN FRAME 434. SCALLOPING EXISTS ALONG BOTH EDGES IN FRAME 522 TO 665 AND 1328 TO 1330. AN IRREGULAR PLUS DENSITY STREAK ABOUT 0.2" WIDE AND LONGITUDINALLY ORIENTED IS PRESENT INTERMITTENTLY IN FRAMES 778 TO 818. A MANUFACTURING SPLICE IS LOCATED IN FRAME 761 WITH ASSOCIATED MINUS DENSITIES ON FRAME 760 AND 761. A HEAT SPLICE IS PRESENT IN FRAME 1018.

C. 9L SIDE: BOTH EDGES CONTAIN MINOR EDGE STATIC DIS-

2-

1

CHARGES THROUGHOUT THE FIRST THIRD OF THE MATERIAL. EDGE FOG IS PRESENT ON BOTH EDGES BUT IS MORE CONSISTENT ON THE OUTBOARD EDGE. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 746 AND 1902. FRAME 1106 CONTAINS A HEAT SPLICE. SMEARED TITLES AND TITLING MATERIAL TRANSFERS ARE NOTED INTERMITTENTLY.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0001-2053.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS DEGRADED OR OBSCURED 20 PERCENT OF THE MISSION PHOTOGRAPHY.

1

S E C R E T

-END OF MESSAGE-